

# LZ SNIPE

GRID: 830764

TA: 16D



Elevation m (ft)	LZ Snipe Center		Slope Degrees	Slope Direction High to Low	Evaluation Adequate/Substandard/Inadequate
	Latitude	Longitude			
109.7 (360.0)	38° 36' 35.91" N	77° 29' 34.27" W	< 1.0	N/A	Inadequate
Perimeter (P) Location					
Location	Latitude	Longitude	Location	Latitude	Longitude
P1	77° 31' 44.57" W	77° 29' 33.30" W	P3	38° 36' 36.24" N	77° 29' 35.50" W
P2	38° 36' 35.50" N	77° 29' 35.21" W	P4	38° 36' 36.82" N	77° 29' 34.00" W
Remarks					
1. Surface conditions consist of loose dirt and gravel.					
2. Large trees line the entire perimeter of the LZ. A gravel access road also lines the eastern perimeter of the LZ.					
3. Area is not suitable to support MV-22 operations.					
4. Facility planners should coordinate with local command to determine utilization of LZ and size and/or improve LZ surface appropriately.					
Obstacle (OB) Location					
OB to LP	Type	Distance m (ft)	Height m (ft)	Width m (ft)	Depth m (ft)
OB1	Tree Line	13.7 (45.0)	18.3 (60.0)	53.3 (175.0)	
OB2	Tree Line	32.0 (105.0)	9.1 (30.0)	18.3 (60.0)	
OB3	Tree Line	21.3 (70.0)	18.3 (60.0)	48.8 (160.0)	
OB4	Tree Line	53.3 (175.0)	18.3 (60.0)	59.4 (195.0)	
Landing Point (LP) Location					
Location	Latitude	Longitude	Location	Latitude	Longitude
LP1	38° 36' 35.91" N	77° 29' 34.27" W			



✦ CENTER MARK  
 ROTOR DOWN-WASH  
 100' X 100' PAD  
 OBSTACLES  
 PERIMETER  
 PERIMETER POINTS

