

# LZ PARROT

GRID: 788734

TA: 14B



Elevation m (ft)	LZ Parrot Center		Slope Degrees	Slope Direction High to Low	Evaluation Adequate/Substandard/Inadequate
	Latitude	Longitude			
94.5 (310.0)	38°35'0.07"N	77°32'30.03"W	6.0	South to North	Substandard
Perimeter (P) Location					
Location	Latitude	Longitude	Location	Latitude	Longitude
P1	38°34'59.14"N	77°32'29.14"W	P3	38°35'1.33"N	77°32'31.58"W
P2	38°34'59.15"N	77°32'31.54"W	P4	38°35'1.47"N	77°32'29.11"W
Remarks					
1.	Surface conditions consist of uneven terrain, loose dirt, grass up to 1.8 m (6.0 ft) tall and trees up to 2.4 m (8.0 ft) tall throughout the LZ.				
2.	LZ sits at the top of a hill.				
3.	LZ is severely overgrown.				
4.	Large trees line the eastern perimeter of the LZ.				
5.	Facility planners should coordinate with local command to determine utilization of LZ and size and/or improve LZ surface appropriately.				
Obstacle (OB) Location					
OB to LZ	Type	Distance m (ft)	Height m (ft)	Width m (ft)	Depth m (ft)
OB1	Tree Line	25.9 (85.0)	18.3 (60.0)	170.7 (560.0)	
OB2	Trees	7.6 (25.0)	2.4 (8.0)	Entire LZ	Entire LZ
OB3	Shed	30.5 (100.0)	2.4 (8.0)	2.4 (8.0)	2.4 (8.0)
Landing Point (LP) Location					
Location	Latitude	Longitude	Location	Latitude	Longitude
LP1	38°35'0.07"N	77°32'30.03"W			